

Прошу обратить внимание!!!!
Клапан на схеме подключен не
правильно!! ПОДАЧА С
НАСОСА И ПОДАЧА НА
БОЧКУ ЭТО СКВОЗНОЕ
ОТВЕРСТИЕ!!!Тройник
подключается в торец (не
сквозное отверстие)

Description : ---
Part N. : ---

Part list			
Item	Part number	Description	Q.ty
1	SERB_S#V2GX0600_H1	OIL TANK 310x440x0600_VL062 [V2] [G] [X MD150-UP]	1
2	SRC#BE-BE	VALVULA DE REGISTRO - 1"1/4 BSPIT - 1"1/4 BSPIT	1
3	PTGF#90ALTG	ELBOW ADAPTER 1"1/4 BSPOT / Ø45 mm + NUT	2
4	TR4#AE1500	SUCTION HOSES R4 - Ø45 x 1500 mm.	1
5	PMP#B0SI	PISTON PUMP BENT AXIS Hd 047 ISO LEFT	1
6	02802500173	PTO IPN. STD. CMB. SCANIA	1
7	D330635	MOUNT. KIT x PTO IPN.STD. CMB. - SCANIA	1
8	DPN#GE	LEVER CAB CONTROLL	1
9	ROB#E	DOWTY WASHER 3/4" BSP	13
10	NPL#ACXAC	STRAIGHT ADAPTER - 3/4" BSPOT - 3/4" BSPOT	9
11	TR2#E2500ZB	LP HOSE 3/4" BSP - L = 2.500 mm - 00° / 90°	1
12	C106910	ADJUSTABLE MAX. PRESSURE VALVE 3/4"	1
13	TR2#E1500ZA	LP HOSE 3/4" BSP - L = 1.500 mm - 00° / 00°	2
14	NPL#AEXAD	STRAIGHT ADAPTER - 1"1/4 BSPOT - 1" BSPOT	1
15	TN#CS	HOSE CONNECTION 3/4" BSPOT	2
16	INNS#AE	QUICK R. COUPLING M.3/4" - ANV	2
17	CPRINNS#HF	PLASTIC CAP 3/4" BSP FEMALE [X.Q.C.ANV]	2
18	CPRINNS#HA	PLASTIC CAP 3/4" BSP MALE [X.Q.C.ANV]	2
19	INNS#AF	QUICK R. COUPLING F.3/4" - ANV	2
20	TN#ZP	HOSE CONNECTION 3/4" BSPIT - 3-WAY	1
21	TR2#E3000ZA	LP HOSE 3/4" BSP - L = 3.000 mm - 00° / 00°	2
22	NPL#ADXAC	STRAIGHT ADAPTER - 1" BSPOT - 3/4" BSPOT	1
23	ROB#G	DOWTY WASHER 1"1/4 BSP	1
24	TR2K#F2500ZB	LP HOSE 1" BSP - L = 2.500 mm - 00° / 90°	1

